




◇ 耐圧検査 (容器再検査) 作業工程



膨張測定試験 (水槽式)



恒久増加率 = 恒久増加 / 全増加 × 100

$0.3/45 \times 100 \div 0.67\%$
10%以上: 不合格

